# **CARVERTICAL**



#### Honda CR-V

VIN: JHMRT6880KX200745


Generated on 05/01/2025, 09:15 PM




Scan for full report











**Data sources** 

We checked 900+ data sources in 35 countries

# **Purpose**


Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!



No issues found

No records of vehicle being used in irregular manner


#### Here's what we checked:




### **Theft**

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

**Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle





#### Police database stolen vehicle check completed in:




### **Odometer**

Are there signs of mileage rollbacks or discrepancies?



- Last known mileage: 16 km
- Average mileage for similar models: 89,885 km
- 1 mileage record found



# Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?



No issues found

No records about the legal status of this vehicle were found

#### Legal



Scrap V No record found No record that vehicle was marked as scrapped

# **Damage**

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).



#### **Damage records**



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

#### **Natural disasters**

Has the vehicle's location been recorded in the area of a natural disaster?



No issues found

Vehicle's location was not recorded in the area of a natural disaster

## **Emissions**

How much CO2 emissions do vehicles of this model/year produce?




carVertical Insight

This vehicle has average emissions. It will likely incur standard emission taxes.

# CO<sub>2</sub> emissions

Emission CO2 g/km



### Specs

What specs and equipment are on record for this vehicle?



Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

### **Identification and technical specifications**



Make

Honda



Model



CR-V


2 L



Powertrain displacement



Powertrain power





Number of seats

CO2 emissions

126 g/km

#### **Timeline**

3 records found

The timeline of records for this vehicle

#### Records

02/2019 () Italy





First registration

The record represents an administrative event. This could be related to a change of ownership, documents, etc

08/2019 () Italy





Ownership changed

The country (or state) has recorded an ownership change or document renewal. Please note that some changes may be formal, e.g., end-of-lease transfers and similar.

10/2022 **| Italy** 





Was deregistered

The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

Data sources

We checked 900+ data sources in 35 countries